



WELL SITE INSPECTION FORM

WELL NAME Perovis #2-19
OPERATOR Morgan/Caray
LOCATION 19, 8N, 92W
FIELD Lay Creek

API NUMBER 05 - 081 - 6600
PERMIT NUMBER #1's not available
COUNTY Moffat
INSPECTOR kmj

AL/PA/DA INSPECTION RESULTS:

PASS(Y) Y FAIL(N) N DATE 5-16-89 WELL STATUS: FN FD WO

DATE OF INSPECTION BEFORE/DURING DRILLING
CASING SIZE DEPTH SET CMT VOL WOC
CONSISTENT WITH APD CASING PROGRAM? RETURNS
RIG BOP'S CONTACT

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION

PIPE SET? COMPLETION RIG/ACTIVITY
DRILLING PITS: CLOSED OPEN WELLHEAD SYSTEM INSTALLED
TANK ID: YES NO NA WELL SIGN: YES NO
SKIM PIT: gal TANKS: () bbls
EQUIPMENT
BRADENHEAD PRESSURE FLUID: NO YES TYPE
METER RUN: YES NO WELL STATUS: PR TA SI WELL CAT 3-

AL/PA/DA INSPECTION

DATE PLUGGED: DATE PERMIT EXPIRED:
HOLE PLUGGED: YES ✓ NO PITS BACKFILLED: YES NO ✓
MATERIAL BURIED: YES NO ✓ NA SITE CLEAN: YES NO ✓
BOND RELEASE OK: YES NO ✓ FED HOLE MARKER: YES NO ✓

DATE OF SAFETY/STATUS INSPECTION

COMMENTS Both holes plugged. Could find evidence of one
hole location. Fenced production pit still on location. Assorted
pipe & timber on location. One stock pond (possible
reserve pit) adjacent to location - dry. Pipe line runs
through location. Pipe w/ flange sticking up.