

Inspection Photos
Location Name: King Location
Location ID# 457362



Akita 518 Drilling ahead



Odor measurement location.

Inspection Photos
Location Name: King Location
Location ID# 457362



Sound meter facing complainant home.



Sound meter facing Knight location.