

# Inspection Photos

2/19/2021

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 398346

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398346



**Photo 1:** Photo taken from the west of the Location, facing northeast. Photos 1-3 provide an overview of the Location from northeast, southeast to south.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 398346



**Photo 2:** See comments under photo 1. Photo also show what appears to be a soil stockpile on the southeast end of the Locaiton.



## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398346



**Photo 3:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398346



**Photo 4:** Photo shows anchor remaining on the northwest corner of the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398346



**Photo 5:** Photo shows anchor remaining on the southeastern area of the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398346



**Photo 6:** Photo shows anchor remaining on the southwest corner of the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398346



**Photo 7:** Photo taken from the northwest end of the Location, facing west. Photo shows access road has not been recontoured, regraded and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398346



**Photo 8:** Photo taken from the west of the Location, facing east. Photo shows access road has not been recontoured, regraded and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources