

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BENTLEY-67S95W /11SENE

Location ID: 324025



Photo #2948 from entrance to location.



Photo #2949 from entrance to location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BENTLEY-67S95W /11SENE

Location ID: 324025



**Photo #2950 Flow line heating insulation open ended and not capped.**