

Inspection Photos
Operator: Simcoe
API: 067-07431
Date: 2/22/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope facing westward. Slope largely snow covered. Perennial vegetation such as western wheatgrass observed in gaps through snow.



Photo 3. View of the eastern project area facing northward.



Photo 4. View of the reference area comprised of pinyon/juniper woodland with shrub understory of mountain mahogany, *Peraphyllum* sp., and sagebrush, and gambel oak.