

Inspection Photos
Operator: Simcoe
API: 067-08211
Date: 2/22/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern fill slope facing eastward. Vegetation is progressing with grasses such as crested wheatgrass and intermediate wheatgrass.



Photo 3. View of the western project area facing northward.



Photo 4. View of the reference area comprised of irrigated grass fields, largely snow covered at this time.