

Inspection Photos
Operator: Simcoe
API: 067-07199
Date: 2/22/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern fill slope facing eastward. Vegetation is progressing with grasses such as western wheatgrass and sand dropseed, as well as forbs such as *Heterotheca villosa*.



Photo 3. View of Russian olive tree within the eastern project area, needs removal.



Photo 4. View of the reference area comprised of pinyon/juniper woodland with gambel oak, antelope bitterbrush, sagebrush understory.