

Inspection Photos
Operator: Simcoe
API: 067-08393
Date: 2/22/2021



Photo 1. View of the eastern project area facing northward.



Photo 2. View of the southern project area facing westward. Little vegetation observed in gaps.



Photo 3. View of musk thistles within the western project area. Approximately 1000 individuals observed.



Photo 4. View of the reference area snow covered at this time.



Photo 5. View of closed gate after leaving location.