

Inspection Photos

2/19/2021

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 315713

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 315713




Photo 1: Photo taken from the west end of the Location, facing northeast. Photo shows Location has not been reclaimed in accordance with COGCC 1004 rules.

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315713



Photo 2: Photo taken from the west end of the Location, facing east. Photo shows Location has not been reclaimed in accordance with COGCC 1004 rules.



Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315713



Photo 3: Photo taken from the north end of the Location, facing northeast. Photo shows area where production equipment (tank) was Location. Photo shows areas have not been reclaimed in accordance with COGCC 1004 Rules.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315713



Photo 4: Photo taken from the north end of the Location, facing west. Photo shows area where production equipment (tank) was Location. Photo shows areas have not been reclaimed in accordance with COGCC 1004 Rules.



Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315713



20210219

Photo 5: Photo taken from the north end of the Location, facing east. Photo shows Location has not been reclaimed in accordance with COGCC 1004 Rules.



Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315713



Photo 6: Photo taken from the east end of the Location, facing west. Photo shows Location has not been reclaimed in accordance with COGCC 1004 Rules.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 315713



Photo 7: Photo taken from the access road, west of the Location, facing east. Photo shows access road/Location has not been reclaimed in accordance with COGCC 1004 Rules.



Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 315713



Photo 8: 2019 COGIS aerial image of the Location. Records show well PA 5/27/2014; Pursuant to Rule 1004.a, surface equipment required to be removed by 8/27/2014, and all reclamation work required to be completed by 5/27/2015. Photo shows equipment (tank) remained on the Location in 2019.

