

# Final Reclamation Inspection

February 23, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

API: 05-123-05445

Inspection Document #: 697502580

Weld County, CO

NENE Section 1 T7N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: BLACK HOLLOWES UT-UPRR #7  
API: 05-123-05445



**Photo 1.** Photo taken from the entrance of the location, facing South. Photo illustrates unmanaged Kochia weeds (some Russian thistle weeds) throughout the entire disturbance area. There was little to no germination of desirable plant species observed throughout the entire disturbance area.



Inspection Photos

Location Name: BLACK HOLLOWES UT-UPRR #7

API: 05-123-05445



**Photo 2.** Close up photo taken from a portion of the access road. Photo illustrates Kochia weeds throughout the entire disturbance area with little to no germination of desirable plant species observed.



Inspection Photos  
Location Name: BLACK HOLLOWES UT-UPRR #7  
API: 05-123-05445



**Photo 3.** Photo taken from the western location, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: BLACK HOLLOWES UT-UPRR #7  
API: 05-123-05445



**Photo 4.** Photo taken from the central location, facing Southeast. See comments under Photo 1.

Inspection Photos  
Location Name: BLACK HOLLOWES UT-UPRR #7  
API: 05-123-05445



**Photo 5.** Reference photo taken west of the location, facing West. See comments under Photo 1.