

Inspection Photos

Location Name: CECIL USX A-66N64W /1SESW

Location #: 306275



Colorado Oil & Gas Conservation Commission
Weld
+40.509732, -104.500327
215° SE
23-Feb-2021 15:35

Photo #1

Cecil USX A 01-14 (05-123-24340) Wellsite

Temporarily Abandoned | TA



Colorado Oil & Gas Conservation Commission
Weld
+40.511324, -104.506342
89° E
23-Feb-2021 15:47

Photo #2

Cecil USX A 01-13, 01-14 Battery site

Abandoned: ALL Equipment Removed