

Inspection Photos

Loc#334336

Operator: Caerus

Insp#: 692403071

Insp Date: 2/23/21





Photo#1:
Overview of Location from entry to Northwest and Interim area.

February 23, 2021



Photo#2:
Valve may be leaking.



Photo#3:
Valve may be leaking.

February 23, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Shideler Loc#334336