

Inspection Photos

Location Name: UPRR 43 PAN AM G Consolidation #2

Remediation No. 16131/ Spill ID: 478086 (CL)



Photo 1 – Spill excavation area. Fencing surrounding open excavation. Groundwater observed in excavation.



Photo 2 – Spill excavation area. Flowline debris present in excavation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources