

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/24/2021

Submitted Date:

02/24/2021

Document Number:

700702351

FIELD INSPECTION FORM

Loc ID 334613 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271441	WELL	PR	07/11/2004	GW	045-09880	SHIDELER 25-12 (L25W)	PR
271446	WELL	PR	07/07/2004	GW	045-09885	SHIDELER 25-14 (L25W)	PR
281337	WELL	PR	08/10/2007	GW	045-11431	SHIDELER 25-14D (L25W)	PR
281339	WELL	PR	02/01/2018	GW	045-11432	SHIDELER 25-13(L25W)	PR
290408	WELL	PR	08/01/2018	GW	045-14108	SHIDELER 25-14A (L25W)	PR
290409	WELL	PR	08/13/2007	GW	045-14107	SHIDELER 25-12C(L25W)	PR
293457	WELL	PR	07/06/2008	GW	045-15000	SHIDELER 25-6 (L25W)	PR
293458	WELL	PR	07/02/2008	GW	045-15001	SHIDELER 25-6C (L25W)	PR
293459	WELL	PR	07/02/2008	GW	045-15002	SHIDELER 25-11D(L25W)	PR
293613	WELL	PR	07/19/2008	GW	045-15070	SHIDELER FEDERAL 25-5C (L25W)	PR
294006	WELL	PR	12/19/2007	GW	045-15198	SHIDELER FEDERAL 26-8C1 (L25W)	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 2/24/2021 at approximately 1400, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus L25W, at Location # 334613 in Garfield county Colorado.

While there, I observed normal production operations. All meters calibrated on location within a year. This location is within a Density Habitat and Wildlife Management Area. Limited storm water inspection due to snow cover.

During this inspection the following possible compliance issues were observed:

1. Tank battery signage does not meet requirements of new rule 605.e
2. Provide proof of tracking control BMP's

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	muddy		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Tank battery signage does not meet requirements of new rule 605.e		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			

Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 10		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 12		
Comment:	All meters calibrated on location within a year.		
Corrective Action:		Date:	
Type: Plunger Lift	# 11		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	271441	Type:	WELL	API Number:	045-09880	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	271446	Type:	WELL	API Number:	045-09885	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	281337	Type:	WELL	API Number:	045-11431	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	281339	Type:	WELL	API Number:	045-11432	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	290408	Type:	WELL	API Number:	045-14108	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	290409	Type:	WELL	API Number:	045-14107	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	293457	Type:	WELL	API Number:	045-15000	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	293458	Type:	WELL	API Number:	045-15001	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	293459	Type:	WELL	API Number:	045-15002	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	293613	Type:	WELL	API Number:	045-15070	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	294006	Type:	WELL	API Number:	045-15198	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: tied into tank battery

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: This location is within a Density Habitat and Wildlife Management Area.

Limited storm water inspection due to snow cover.

1. Provide proof of tracking control BMP's

Corrective Action: 1. Install, maintain or provide documentation of post construction management plan or BMP's

Date: 03/24/2021

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702353	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5360415