

Inspection Photos
Location Name: Klein #1
Location ID: 318289



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Klein #1
Location ID: 318289



Photo 3 leak below plunger lift has been repaired