

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/19/2021

Submitted Date:

02/24/2021

Document Number:

688309735**FIELD INSPECTION FORM**Loc ID 316948 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10690Name of Operator: IMPETRO RESOURCES LLCAddress: 2820 LOGAN DRIVECity: LOVELAND State: CO Zip: 80538**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bradley, Sam	970-593-8626	sbradley.impetro@gmail.com	Principal Agent
Quint, Craig		craig.quint@state.co.us	
Morgan, John		john.morgan@state.co.us	
Gibson, Rick	970-768-6880	rtgibson01@msn.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
233400	WELL	TA	02/01/2020	OW	121-05438	COWLES 4	WO

**General Comment:**New UIC MIT, passed, Form 21 attached

**Inspected Facilities**Facility ID: 233400 Type: WELL API Number: 121-05438 Status: TA Insp. Status: WO**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: JSND

TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: 04/02/2019

Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: 5 Year Tbg psi: 0 Csg psi: 0 BH psi: 0Insp. Status: Pass

Comment: MIT  
0 min 390 psi  
5 min 390 psi  
10 min 390 psi  
15 min 390 psi  
0 psi after test  
Form 21 is attached. Operator to submit within 10 days of test.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688309803	Impetro Cowles 4 UIC MIT Form 21	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5360585">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5360585</a>
688309804	Impetro Cowles 4	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5360586">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5360586</a>