

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/22/2021

Submitted Date:

02/25/2021

Document Number:

691201405**FIELD INSPECTION FORM**Loc ID 475322 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
Canfield, Chris		chris.canfield@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
Knop, Max	303-825-4822	MKnop@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477437	SPILL OR RELEASE	AC	08/04/2020		-	Yoxall Farms Manifold	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Spill remains open.Corrective Action: As per CA on Insp Document #689501099: Submit a Supplemental Form 27 requesting closure of Spill ID 477437 with work being performed under Remediation Project No. 15961. Submit a Form 27 Supplemental Report within 45 days of performing the environmental site investigationDate: 11/26/2020

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:Comment: Form 27I (Document #402486281) listed a start date for remediation as 10/19/2020. As of inspection no work has been completed.Corrective Action: Per Rule 913.d.(2) Operator shall submit a Supplemental Form 27 with an updated Implementation Schedule at least 14 days in advance.Date: 10/05/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691201406	Site Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5361025