

## Inspection Photos

Location Name: Lawrence Totems Consolidation Line

Remediation Project No. 15811/Spill ID 477024



**Photo 1 – Potholed spill area**



**Photo 2 – Spill area; soils stored on location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources