


Inspection Photos

Location Name: CECIL USX A-66N64W /1NWSE

Location #: 332935



Colorado Oil & Gas Conservation Commission
Weld
+40.513762, -104.495967
310° NW
24-Feb-2021 15:32

Photo #1

Cecil USX A 01-11D (05-123-29787) Wellsite
Plugged & Abandoned | PA
~ 25 yds.



Colorado Oil & Gas Conservation Commission
Weld
+40.515291, -104.498441
130° SE
24-Feb-2021 15:38

Photo #2

**Cecil USX A 1-10, 01-01, 01-02, 01-05 D, 1-6, 1-7,
01-08, 01-09, 1-17, 1-19 Battery site**
Abandoned: ALL Equipment removed
Formerly served:
Cecil USX A 01-11D, 01-03, 01-04
Plugged & Abandoned | PA