

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/24/2021

Submitted Date:

02/25/2021

Document Number:

696104394**FIELD INSPECTION FORM**

Loc ID 332935	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 14 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>100322</u> Name of Operator: <u>NOBLE ENERGY INC</u> Address: <u>1001 NOBLE ENERGY WAY</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77070</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287480	WELL	TA	05/04/2020	GW	123-24341	Cecil USX A 1-10	TA

General Comment:

This is a WELL / ABANDONED BATTERY inspection.
 Well(s): 1: Temporarily Abandoned | TA.
 Battery: Abandoned. ALL equipment has been removed.
 Abandoned Battery SE corner GPS coordinates: 40.515001 / -104.497637

Abandoned Centralized Battery formerly served 11 Location IDs.
 (332935, 302408, 302409, 302410, 302413, 302414, 302415, 306355, 310486, 310487, 333048).
 (Well(s): 10: Temporarily Abandoned | TA ; 3: Plugged & Abandoned | PA).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 0		
Comment:	Battery Abandoned. Equipment removed.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 0		
Comment:	Battery Abandoned. Equipment removed.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:	Battery Abandoned. Equipment removed.		
Corrective Action:		Date:	

Type: Emission Control Device	# 0	
Comment:	Battery Abandoned. Equipment removed.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:	Battery Abandoned. Equipment removed.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment:	Battery Abandoned. Equipment removed.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 287480 Type: WELL API Number: 123-24341 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned: All Equipment Removed.
COGCC records indicate last production: 02/2017.
SI/TA well per variance doc. #401474555. (NOBLE).
Yellow LTSI tag for SI/TA status present at wellsite.
Locked-Out, Tagged-Out | LOTO.

Form 4 Sundry doc. #402373759, Temporarily Abandoned | TA status date:12/13/2018.
Approved.

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 10/04/2019 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: _____End Surf Csg Pressure: --

Comment: No record of Brhd test within last 12 months. Refer to Rule 206.
Submit current Brhd test. Comply w/ Rule 206.
Contact COGCC Engineering.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 02/24/2021 at approximately 15:28 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: CECIL USX A-66N64W /1NWSE Location ID: 332935 Well Name: Cecil USX A 1-10 API: 05-123-24341 Location County: Weld County, Colorado Weather: Overcast, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.515001 / -104.497637</p> <p>Abandoned Centralized Battery formerly served 11 Location IDs. (332935, 302408, 302409, 302410, 302413, 302414, 302415, 306355, 310486, 310487, 333048). (Well(s): 10: Temporarily Abandoned TA ;3: Plugged & Abandoned PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/25/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104395	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5361511