

Inspection Photos

2/24/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324411

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324411



Photo 1: Photo taken from the access road entrance from the main lease road, facing southwest. Signage required per the NTO not observed and access road or location entrance.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 324411



Photo 2: Photo taken from the location entrance, facing southwest. Signage required per the NTO not observed on access road or location entrance.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324411



Photo 3: Photo of the one PR well on the Locaiton.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324411



Photo 4: Photo taken from the southern end of the Location, facing north. Photos 4-6 provide and overview of the Location from north, northeast to southeast. Interim reclamation due on Location 5/10/2021.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 324411



Photo 5: See comments under photo 4.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324411



Photo 6: See comments under photo 4.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 324411



Photo 7: Photo taken from the northeast end of the Location, facing south. Photo provides an overview of the Location and pits. Interim reclamation due on Location 5/10/2021.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 324411



Photo 8: Photo taken from the northeast end of the Location, facing southwest. Photo provides an overview of the Location and pits. Interim reclamation due on Location 5/10/2021.