

Inspection Photos
Location Name: Robert G Berge #2
Remediation Project No. 15743/ Spill ID 476918 (CL)



Photo 1 – Spill area. No fencing around open excavation



Photo 2 – Spill area; groundwater observed in the excavation



Inspection Photos
Location Name: Robert G Berge #2
Remediation Project No. 15743/ Spill ID 476918 (CL)



Photo 3 – Soils stored on location



Photo 4 – Soils stored on location; BMPs inadequate to contain runoff



Inspection Photos
Location Name: Robert G Berge #2
Remediation Project No. 15743/ Spill ID 476918 (CL)



Photo 5 – Soils stored on location; BMPs inadequate to contain runoff



Photo 6 – Soils stored on location; BMPs inadequate to contain runoff

