

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/24/2021

Submitted Date:

02/25/2021

Document Number:

700405543**FIELD INSPECTION FORM**
 Loc ID 398836 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 110 W 7TH STREETCity: FORT WORTH State: TX Zip: 76102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-------------------------------|---------|
| Clark, Erin | 405-319-3250 | erin_clark@xtoenergy.com | |
| Dooling, Jessica | 970-675-4122 | jessica_dooling@xtoenergy.com | |
| West, Jerry | | jerry_west@xtoenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------------|-------------|
| 301740 | WELL | PR | 07/17/2009 | GW | 103-11465 | PICEANCE CREEK UNIT 297-11C5 | PR |
| 301741 | WELL | PR | 05/29/2012 | GW | 103-11466 | PICEANCE CREEK UNIT 297-11C4 | PR |
| 301742 | WELL | SI | 12/01/2020 | GW | 103-11467 | Piceance Creek Unit 297-11C8 | SI |
| 301743 | WELL | PR | 02/01/2020 | GW | 103-11468 | PICEANCE CREEK UNIT 297-11C1 | PR |
| 301744 | WELL | PR | 09/08/2010 | GW | 103-11469 | Piceance Creek Unit 297-11C7 | PR |
| 301745 | WELL | PR | 09/18/2010 | GW | 103-11470 | PICEANCE CREEK UNIT 297-11C2 | PR |
| 301746 | WELL | PR | 07/17/2009 | GW | 103-11471 | Piceance Creek Unit 297-11C9 | PR |
| 301747 | WELL | PR | 07/17/2009 | GW | 103-11472 | PICEANCE CREEK UNIT 297-11C6 | PR |
| 301748 | WELL | PR | 07/17/2009 | GW | 103-11473 | PICEANCE CREEK UNIT 297-11C3 | PR |

General Comment:

Routine well inspection.

LocationOverall Good: ☒

| | | | |
|----------------------|----------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Location sign. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|----------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Other | # 1 | | |
| Comment: | RTU building. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Chemical containers. | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 9 | | |
| Comment: | Bradenhead access. | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 10 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |

| | | | |
|--------------------|-----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 9 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 301740 | Type: | WELL | API Number: | 103-11465 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 301741 | Type: | WELL | API Number: | 103-11466 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 301742 | Type: | WELL | API Number: | 103-11467 | Status: | SI | Insp. Status: | SI |
| Idle Well | | | | | | | | | |
| Purpose: | <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____ | | | | | | | | |
| Comment: | Last recorded production November 2020. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 301743 | Type: | WELL | API Number: | 103-11468 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 301744 | Type: | WELL | API Number: | 103-11469 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 301745 | Type: | WELL | API Number: | 103-11470 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 301746 | Type: | WELL | API Number: | 103-11471 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 301747 | Type: | WELL | API Number: | 103-11472 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| <u>Producing Well</u> | | | |
|---|----|-------|--|
| Comment: | PR | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>301748</u> Type: <u>WELL</u> API Number: <u>103-11473</u> Status: <u>PR</u> Insp. Status: <u>PR</u> | | | |
| <u>Producing Well</u> | | | |
| Comment: | PR | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Rip Rap | | | | | | |
| Gravel | | Gravel | | Material Handling And Spill Prevention | | |

Comment: 2" of snow on location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 700405544 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5361782 |