

Inspection Photos
Location Name: Caerus #10456
Location: 334872

NE E SE
30 60 90 120 150
81°E (T) 39°26'40"N, 107°41'13"W ±16ft ▲ 6179ft



SE S SW
120 150 180 210 240
170°S (T) 39°26'41"N, 107°41'13"W ±16ft ▲ 6164ft



Inspection Photos
Location Name: Caerus # 10456
Location: 334872



Looking south on CR 315



Open manway on production tanks

Inspection Photos
Location Name: Caerus # 10456
Location: 334872



**Production tank removed from containment for repairs.
Manway is open, not secondary containment.**



**Production tanks removed from containment, and propped
at an angle by wooden blocks.**

Inspection Photos
Location Name: Caerus # 10456
Location: 334872



Debris and trash laying on pad surface.



Equipment is stored on pad surface.

Inspection Photos
Location Name: Caerus # 10456
Location: 334872



Material storage on pad surface.



Soil storage on location.