

Inspection Photos
Operator: Simcoe
API: 067-08423
Date: 2/24/2021



Photo 1. View of the eastern project area from the southwestern corner facing center.



Photo 2. View of the western project area facing northward. Vegetation appears to be progressing in with blue grama and sand dropseed. Snow covered areas need to be assessed during the active growing season.



Photo 3. View of the southern project area facing eastward. Soils in this portion of the project area are recently disturbed and need revegetation within the spring planting window.



Photo 4. View of the reference area comprised of perennial irrigated grasses such as smooth brome, partially snow covered at this time.