

Inspection Photos

API: 011-06090

Operator: OXY USA INC

Inspection Date: 2/23/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 011-06090 | Date: 2/23/2021

Inspection Photos



Photo 1. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06090 | Date: 2/23/2021

Inspection Photos



Photo 2. Facing east at the location. Vegetation is sparse in areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06090 | Date: 2/23/2021

Inspection Photos



Photo 3. Facing northwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06090 | Date: 2/23/2021

Inspection Photos



Photo 4. Facing west at the location. It appears vegetation establishment has improved at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06090 | Date: 2/23/2021