

# Inspection Photos

API: 011-06060

Operator: STRACHAN EXPLORATION INC

Inspection Date: 2/23/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 011-06060 | Date: 2/23/2021

## Inspection Photos



**Photo 1.** Facing southwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 011-06060 | Date: 2/23/2021

## Inspection Photos



**Photo 2.** Facing toward the tank battery.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 011-06060 | Date: 2/23/2021



## Inspection Photos



**Photo 3.** Facing toward the wellhead which has been disassembled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 011-06060 | Date: 2/23/2021