

Inspection Photos
Location Name: McCallum 129
Location ID: 324720



Photo 1. Overview of location taken facing northwest.



Inspection Photos
Location Name: McCallum 129
Location ID: 324720



Photo 2. No bradenhead access apparent.



Photo 3. Stained soil at wellhead.

