

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/17/2021

Submitted Date:

02/17/2021

Document Number:

701002391**FIELD INSPECTION FORM**Loc ID 321827 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 61250

Name of Operator: MULL DRILLING COMPANY INC

Address: 1700 N WATERFRONT PKWY B#1200

City: WICHITA State: KS Zip: 67206-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Akers, Tracy	719-342-1813	takers@mulldrilling.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208134	WELL	PR	11/30/2004	OW	017-07069	NW ARAPAHOE UNIT (NWAU) 20	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Gravel road through farm ground		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Sticker on chemical tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Lufkin 320		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Electric panel, telemetry equipment and chemical tanks w/containment		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	208134	Type:	WELL	API Number:	017-07069	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central tank battery for (NWAU 20, 21 & 22) 1900' NE @ 38.885680/-102.119460								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701002403	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5362737