

Inspection Photos

API: 099-06255

Operator: BERRY* WALTER V DBA BERRY
ENERGY INC

Inspection Date: 2/23/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 099-06255 | Date: 2/23/2021

Inspection Photos



Photo 1. Facing northwest along the former access road to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06255 | Date: 2/23/2021

Inspection Photos



Photo 2. Facing west at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06255 | Date: 2/23/2021

Inspection Photos



Photo 3. Facing south at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06255 | Date: 2/23/2021

Inspection Photos



Photo 4. Facing west at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06255 | Date: 2/23/2021

Inspection Photos



Photo 5. Facing north at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06255 | Date: 2/23/2021

Inspection Photos



Photo 6. There is a pipe riser that remains at the north side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06255 | Date: 2/23/2021

Inspection Photos



Photo 7. Facing northwest approximately 1400 ft. northwest of the location There are two pipe risers associated with the well site that have not been removed. All equipment/risers must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06255 | Date: 2/23/2021