

Inspection Photos

Loc#324340

Operator: Caerus

Insp#: 692403074

Insp Date: 2/23/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to Northwest.

February 23, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Encore West Loc#324340



Photo#2:
Tank containment area.



Photo#3:
View along Fill Slope.

February 23, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Encore West Loc#324340