

Inspection Photos

Loc#334232

Operator: Caerus

Insp#: 692403077

Insp Date: 2/23/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to Northwest.

February 23, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Shideler Loc#334232



Photo#2:
Interim area.



Photo#3:
Overview of Location from entry to Southeast.

February 23, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Shideler Loc#334232