

# *Inspection Photos*

*Loc#334630*

*Operator: Caerus*

*Insp#: 692403079*

*Insp Date: 2/23/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry to Northwest and both legs of site.

February 23, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Shideler Loc#334336



Photo#2:  
View over West leg.



Photo#3:  
Interim area.

February 23, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Shideler Loc#334336