

# *Inspection Photos*

*Loc#324349*

*Operator: Caerus*

*Insp#: 692403080*

*Insp Date: 2/23/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry to East.

February 23, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus HMU Loc#324349



Photo#2:  
Interim areas.



Photo#3:  
View to West over containment.

February 23, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus HMU Loc#324349