

Inspection Photos
Location Name: Greasewood 10-20H
Location ID: 423614



Photo 1 – Tank Battery



Photo 2 – Tank Battery Signs

Inspection Photos
Location Name: Greasewood 10-20H
Location ID: 423614



Photo 3 – Risers have been marked




Photo 4 – Production Equipment



Inspection Photos
Location Name: Greasewood 10-20H
Location ID: 423614



Photo 5 – Pumping Unit



Photo 6 – Wellhead