

Inspection Photos

API: 071-06213

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/1/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06213 | Date: 3/1/2021

Inspection Photos



Photo 1. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06213 | Date: 3/1/2021

Inspection Photos



Photo 2. Water level in the pit is above freeboard and needs to be lowered.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06213 | Date: 3/1/2021

Inspection Photos



Photo 3. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06213 | Date: 3/1/2021

Inspection Photos



Photo 3. The sediment trap has filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06213 | Date: 3/1/2021