

# *Inspection Photos*

*Loc#335046*

*Operator: Grizzly*

*Insp#: 692403101*

*Insp Date: 2/25/21*





Photo#1:  
Overviews of Location.

February 25, 2021



Photo#2:  
Showing effects of high animal impact  
/heavy grazing pressure.

February 25, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#3:  
Vegetation appears sparse and weedy.

Grizzly Miller Loc#335046