

Inspection Photos

Loc#335079

Operator: Grizzly

Insp#: 692403103

Insp Date: 2/25/21





Photo#1:
Overview of Location from entry to Northwest.

February 25, 2021



Photo#2:
Overview of Location to Southeast.

February 25, 2021



Photo#3:
Interim areas.



Photo#4:
Interim areas.

February 25, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly ScotLoc#335079