

# Inspection Photos

API: 071-06441

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/1/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06441 | Date: 3/1/2021

## Inspection Photos



**Photo 1.** Facing east along the access road. There is erosion along the side of the road ascending the hill towards the gate which leads to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06441 | Date: 3/1/2021

Inspection Photos



**Photo 3.** Facing northeast toward the location.



## Inspection Photos



**Photo 3.** What appears to be a tarp roller off a dump truck lays next to the meter shed. Unused equipment needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06441 | Date: 3/1/2021