

Inspection Photos

Loc#323957

Operator: Caerus

Insp#: 692403115

Insp Date: 2/26/21





Photo#1:
Overview of Location to Southwest.

February 26, 2021



Photo#2:
Interim area.



Photo#3:
Equipment area.

February 26, 2021