

Inspection Photos
Location Name: North Platte 14-34 Pad
Location ID: 428272



Photo #1 Location

Photo #2 Wells

Inspection Photos
Location Name: North Platte 14-34 Pad
Location ID: 428272



Photo #3 Unused Equipment "Fence"

Photo #4 Trash "cement"

Inspection Photos
Location Name: North Platte 14-34 Pad
Location ID: 428272




Photo #5 Unused Equipment “motor valve”

Photo #6 Unused Equipment “downhole tool”

Inspection Photos
Location Name: North Platte 14-34 Pad
Location ID: 428272



Photo #7 Unused Equipment "fence post"

Photo #8 Stained soil

Inspection Photos
Location Name: North Platte 14-34 Pad
Location ID: 428272



Photo #9 Stained soil

Photo #10 Leaking Master Valve

Inspection Photos
Location Name: North Platte 14-34 Pad
Location ID: 428272



Mar 2, 2021 at 9:19:39 AM
+40.3503,-104.4303
Weld

Colorado Oil & Gas Conservation Commission



Mar 2, 2021 at 9:19:47 AM
+40.3503,-104.4303
Weld

Colorado Oil & Gas Conservation Commission

Photo #11 Stained soil

Photo #12 Leaking Master Valve

Inspection Photos
Location Name: North Platte 14-34 Pad
Location ID: 428272



Photo #13 Stained soil



Photo #14 Leaking Master Valve

Inspection Photos
Location Name: North Platte 14-34 Pad
Location ID: 428272



Photo #15 Stained soil



Photo #16 Leaking Master Valve

Inspection Photos
Location Name: North Platte 14-34 Pad
Location ID: 428272



Photo #17 Stained soil



Photo #18 Leaking Master Valve

Inspection Photos
Location Name: North Platte 14-34 Pad
Location ID: 428272



Photo #19 Stained soil



Photo #20 Leaking Master Valve

Inspection Photos
Location Name: North Platte 14-34 Pad
Location ID: 428272



Photo #21 Trash

Photo #22 Trash

Inspection Photos
Location Name: North Platte 14-34 Pad
Location ID: 428272



Photo #23 Pig Station

Photo #24 Trash

Inspection Photos
Location Name: North Platte 14-34 Pad
Location ID: 428272



Mar 2, 2021 at 9:21:46 AM
+40.3498, -104.4303
Weld
Colorado Oil & Gas Conservation Commission



Mar 2, 2021 at 9:21:58 AM
+40.3498, -104.4303
Weld
Colorado Oil & Gas Conservation Commission

Photo #25 Weathered Berm

Photo #26 Weathered Berm

Inspection Photos
Location Name: North Platte 14-34 Pad
Location ID: 428272



Photo #27 Weathered Berm

Photo #28 Weathered Berm