

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #1 Location



Photo #2 Tank Battery



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #3 Stains



Photo #4 Stains and stained gravel



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #5 Stains



Photo #6 Stain/ Mechanical condition

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #7 Trash



Photo #8 Trash

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #9 Unused Equipment



Photo #10 Trash

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #11 Faded Placard



Photo #12 Faded Placard



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #13 Faded Placard



Photo #14 Faded Placard



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #15 Faded Placard



Photo #16 Faded Placard

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #17 Wells



Photo #18 Trash/ Unused equipment

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #19 Weathered berm



Photo #20 Weathered berm

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #21 Unused equipment




Photo #22 Stained soil/ Oily skid



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #23 Stained soil/ Oily skid




Photo #24 Oily skid



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #25 Stained soil



Photo #26 Stained soil/ Oily skid



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #27 Stained soil/ Oily skid



Photo #28 Stained soil/ Oily waste in bucket

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #29 Stained soil/ Oily waste in bucket/ Oily skid



Photo #30 Stained soil/ Oily waste in bucket/ Oily skid

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #31 Stained soil/ Oily skid



Photo #32 Stained soil

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #33 Stained soil



Photo #34 Stained soil/ Unused Equipment "Can"



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #35 Stained soil/ Oily skid



Photo #36 Weathered berm

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #37 Weathered berm



Photo #38 Unmarked Riser

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #39 Unmarked Riser



Photo #40 Unmarked Riser

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #41 Unmarked Riser



Photo #42 Unmarked Riser



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #43 Unmarked Riser



Photo #44 Unmarked Riser

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #45 Unmarked Riser



Photo #46 Unmarked Riser



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #47 Unmarked Riser



Photo #48 Unmarked Riser

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #49 Unmarked Riser



Photo #50 Unmarked Riser

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #51 Unmarked Riser



Photo #52 Stained soil by VRU

Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #53 Weathered berm



Photo #54 Unused Equipment



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #55 Unused Equipment



Photo #56 Unused Equipment



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #57 Mechanical Conditions/ oil stained equipment



Photo #58 Mechanical Conditions/ Stained soil



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #59 Mechanical Conditions/ Stained soil



Photo #60 Stained Soil



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #61 Stained Soil



Photo #62 Stained Soil



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #63 Mechanical Conditions/ Stained Soil



Photo #64 Mechanical Conditions/ Stained Equipment



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084




Photo #65 Needs Secondary containment



Inspection Photos
Location Name: North Platte 24-34 Pad
Facility ID: 447084



Photo #66 Missing Gas Meter Calibration Card



Photo #67 Missing Gas Meter Calibration Card