



Inspection Photos
Well 107-06175
Inspection Date: 3/1/2021
All Photos taken by Kris Neidel

Photo #1 taken from county rd 59. location was snowed in, appeared that no snow had been plowed this winter. Note: tank battery for reference.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Well 107-06175

Inspection Date: 3/1/2021

All Photos taken by Kris Neidel

Photo #2 Dry Creek UT HD 31 1A well can be seen on right side of photo. The well had a pump string with no pumping unit. The shed on left side of photo is water well, permit # 66138-F.



Inspection Photos

Well 107-06175

Inspection Date: 3/1/2021

All Photos taken by Kris Neidel

Photo #3 close up of water well shed. The shed had cyclone fencing around it. Appeared to be padlocked. COGCC did not attempt to enter the fencing or shed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Well 107-06175

Inspection Date: 3/1/2021

All Photos taken by Kris Neidel

Photo #5 TA well, close-up of signage.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Well 107-06175

Inspection Date: 3/1/2021

All Photos taken by Kris Neidel

Photo #6 well close-up



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Well 107-06175
Inspection Date: 3/1/2021
All Photos taken by Kris Neidel

Photo #7 well close up.



Inspection Photos

Well 107-06175

Inspection Date: 3/1/2021

All Photos taken by Kris Neidel

Photo #8 Tank Battery, note cyclone fencing.



Inspection Photos

Well 107-06175

Inspection Date: 3/1/2021

All Photos taken by Kris Neidel

Photo #9 close-up of signage at location. Tank is labeled “Motor Oil” and “crude oil”



Inspection Photos
Well 107-06175
Inspection Date: 3/1/2021
All Photos taken by Kris Neidel

Photo #10 tank battery. Dirt berm.



Inspection Photos
Well 107-06175
Inspection Date: 3/1/2021
All Photos taken by Kris Neidel

Photo #11 Inside tank battery looking southeast.