

Inspection Photos

3/1/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 335795

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335795



Photo 1: Photo taken from the north end of the Location, facing south. Photo provides an overview of the Location. Photo also shows rutting and tracking issues observed on the Location. Photo also shows areas where stormwater ponding on the Location is evident; Pad does not appear to have been constructed to allow for proper stormwater discharge



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335795



Photo 2: Photo shows example of marked anchors on the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335795




Photo 3: Photo taken from the west end of the Location, facing north. Desirable perennial vegetative establishment observed on slopes.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335795



Photo 4: Photo taken from the interim areas. Photo shows desirable perennial vegetative establishment is evident. Cheat grass and heavy grazing pressure also evident throughout interim areas.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335795



Photo 5: Photo of tanks battery and signage.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335795



Photo 6: Photo taken from the eastern interim areas of the Location, facing south. See comments under photo 5

