

Inspection Photos

3/1/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 324198

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 324198



Photo 1: Photo taken from the north end of the Location, facing south. Photo provides an overview of the Location. Photo also shows pad stabilization, rutting and tracking issues observed on the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324198



Photo 2: Photo taken from the northeast end of the Location, facing west. Photo shows pad stabilization, rutting and tracking issues observed on the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324198



Photo 3: Photo taken from the east end of the Location, facing east. Photo shows sediment trap with armored outlet.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324198



Photo 4: Photo taken from the south end of the Location, facing east. Photo shows perimeter stormwater ditch. Ditch currently discharges directly from pad onto the adjacent interim areas/lands; Ditch has not been constructed with an outlet to allow for sediment laden-free stormwater discharge



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324198



Photo 5: Continued from photo 4. Ditch currently discharges directly from pad onto the adjacent interim areas/lands; Ditch has not been constructed with an outlet to allow for sediment laden-free stormwater discharge



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324198



Photo 6: Photo of well and signage.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324198



Photo 7: Photo of tank battery and signage.

