

**Inspection Photos**  
**Location Name: Wolf 35-2623H**  
**Location ID: 426053**



**Photo 1 – Pumping Unit**

**Photo 2 – Tank Battery Sign**

**Inspection Photos**  
**Location Name: Wolf 35-2623H**  
**Location ID: 426053**



**Photo 3 – Tank Battery**

**Photo 4 – Heater Treaters**

**Inspection Photos**  
**Location Name: Wolf 35-2623H**  
**Location ID: 426053**



**Photo 5 – Unmarked Risers**



**Photo 6 – Stained Soil at Exhaust**

**Inspection Photos**  
**Location Name: Wolf 35-2623H**  
**Location ID: 426053**



**Photo 7 – Stained Soil at Engine**

**Photo 8 – Unused Tank on North end of Location**

**Inspection Photos**  
**Location Name: Wolf 35-2623H**  
**Location ID: 426053**



**Photo 9 – Flares**