

Inspection Photos
Location Name: Perkins-Thornburg 1
Location ID: 320023

Mar 2, 2021 at 2:10:03 PM
39.768517,-104.393148
881 Provost Rd
Bennett CO 80102
United States
COGCC



Pic 1

Mar 2, 2021 at 2:10:26 PM
39.768602,-104.393068
881 Provost Rd
Bennett CO 80102
United States
COGCC



Pic 2 storage of equipment

Inspection Photos
Location Name: Perkins-Thornburg 1
Location ID: 320023

Mar 2, 2021 at 2:14:08 PM
39.768742,-104.393256
881 Provost Rd
Bennett CO 80102
United States
COGCC



Pic 3 unused equipment on location

Mar 2, 2021 at 2:14:43 PM
39.768804,-104.393282
881 Provost Rd
Bennett CO 80102
United States
COGCC



Pic 4 mechanical issue with separator

Inspection Photos
Location Name: Perkins-Thornburg 1
Location ID: 320023

Mar 2, 2021 at 2:17:32 PM
39.768949,-104.393702
881 Provost Rd
Bennett CO 80102
United States
COGCC



Pic 5 unused equipment by pump jack