

# Inspection Photos

3/1/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 335818

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335818



**Photo 1:** Photo taken from the north end of the Location, facing east. Photos 1-5 provide an overview of the Location from east, southeast, south, southwest to west. Pad has been graveled and is stabilized.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335818



**Photo 2:** See comments under photo 1.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335818



**Photo 3:** See comments under photo 1.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335818



**Photo 4:** See comments under photo 1.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335818



**Photo 5:** See comments under photo 1.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335818



**Photo 6:** Photo of wells and signage.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335818



**Photo 7:** Photo taken from the southern areas of the Location, facing east. Photo shows interim areas, and the sediment trap/pond. Desirable perennial vegetative establishment observed on interim areas; interim reclamation appears to be progressing towards 1003 standards. Evidence of heavy grazing also observed.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335818



**Photo 8:** Photo taken from the southern areas of the Location, facing west. Photo shows lower section of the Pad. Production areas have been stabilize with gravel; not immediate stormwater concerns observed.

