

Inspection Photos
Location Name:
State Pronghorn 44-32 Pad
Location ID: 441121



Photo #1 Location

Inspection Photos
Location Name:
State Pronghorn 44-32 Pad
Location ID: 441121



Photo #2 Wells




Photo #3 Wells

Inspection Photos
Location Name:
State Pronghorn 44-32 Pad
Location ID: 441121



Photo #4 Stained soil/ Mechanical Conditions



Photo #5 Stained soil/ Mechanical Conditions

Inspection Photos
Location Name:
State Pronghorn 44-32 Pad
Location ID: 441121



Photo #6 Stained soil



Photo #7 Leaking master valve "Mechanical Conditions"

Inspection Photos
Location Name:
State Pronghorn 44-32 Pad
Location ID: 441121



Photo #8 Weathered Berm



Photo #9 Weathered Berm

Inspection Photos
Location Name:
State Pronghorn 44-32 Pad
Location ID: 441121



Photo #10 Weathered Berm



Photo #11 Leak

Inspection Photos

Location Name:

State Pronghorn 44-32 Pad

Location ID: 441121



Photo #12 Knocked over fence



Photo #13 Stained soil



Inspection Photos

Location Name:

State Pronghorn 44-32 Pad

Location ID: 441121



Photo #14 Leaking Master valve “mechanical conditions”



Photo #15 Stained soil/ Mechanical condntions



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name:

State Pronghorn 44-32 Pad

Location ID: 441121



Photo #16 Stained soil



Mar 3, 2021 at 10:36:47 AM
+40.3516, -104.2272
Weld

Colorado Oil & Gas Conservation Commission

Photo #17 Unused Equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name:
State Pronghorn 44-32 Pad
Location ID: 441121



Photo #18 Unused Equipment



Photo #19 Stained Soil

Inspection Photos
Location Name:
State Pronghorn 44-32 Pad
Location ID: 441121



Photo #20 Stained Soil



Photo #21 Oily Waste

Inspection Photos
Location Name:
State Pronghorn 44-32 Pad
Location ID: 441121



Photo #22 Stained Soil/ Trash



Photo #23 Mechanical conditions/ stained separator.



Inspection Photos

Location Name:

State Pronghorn 44-32 Pad

Location ID: 441121



Photo #24 Mechanical conditions/ stained separator.



Photo # 25 Stained Soil

Inspection Photos
Location Name:
State Pronghorn 44-32 Pad
Location ID: 441121



Photo #26 Unused Equipment



Photo #27 Not LO/TO Risers

Inspection Photos

Location Name:

State Pronghorn 44-32 Pad

Location ID: 441121



Photo #28 Not LO/TO Riser



Photo #29 Not LO/TO Riser