

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402610060

Date Received:

02/26/2021

Spill report taken by:

CANFIELD, CHRIS

Spill/Release Point ID:

479427

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Operator No: <u>47120</u>	Phone Numbers
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 515-1698</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80217-3779</u>
Contact Person: <u>Greg Hamilton</u>		Mobile: <u>()</u>
		Email: <u>Gregory_Hamilton@oxy.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402603770

Initial Report Date: 02/19/2021 Date of Discovery: 02/18/2021 Spill Type: Recent Spill

Spill/Release Point Location:

QTRQTR SWSE SEC 33 TWP 3N RNG 68W MERIDIAN 6Latitude: 40.176577 Longitude: -105.003396Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: WELL PAD☒ Facility/Location ID No 449884Spill/Release Point Name: Newby 15-33HZ☐ Well API No. (Only if the reference facility is well) 05- -☐ No Existing Facility or Location ID No.

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): UnknownEstimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): _____

Weather Condition: Sunny 40°FSurface Owner: FEE

Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On February 18, 2021, produced water released from the main water trunk line at the Newby 15-33HZ facility. Assessment activities are ongoing. The assessment details will be summarized in a supplemental report. The topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
2/18/2021	Weld County	Weld County	-	Notified via Email
2/18/2021	City of Longmont	Landowner	-	Notified via Email

Was there a Grade 1 Gas Leak? Yes ☐ No ☒

If YES, enter the Document Number of the Grade 1 Gas Leak Report Form 44: _____

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: _____

Was there damage during excavation? Yes ☐ No ☒

If YES, was CO 811 notified prior to excavation? Yes ☐ No ☐

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 02/26/2021		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER			<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO			
Secondary containment, including walls & floor regardless of construction material , must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): _____		Width of Impact (feet): _____	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined?			
Assessment and remediation activities are ongoing. Confirmation soil samples will be collected from the excavation areas for laboratory analysis of the full Table 915-1 list for soil (as applicable). The analytical results and assessment details will be provided in a supplemental report.			
Soil/Geology Description:			
TBD			
Depth to Groundwater (feet BGS) 10		Number Water Wells within 1/2 mile radius: 7	

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
402610060	SPILL/RELEASE REPORT(SUPPLEMENTAL)
402610067	TOPOGRAPHIC MAP
402616731	FORM 19 SUBMITTED

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)